

CERNY ξ IVEY ENGINEERS, INC.

CONSULTING ENGINEERS - TESTING LABORATORY 5650 PEACHTREE PARKWAY, NORCROSS, GA 30092 TEL 770-449-6936 - FAX 770-368-1148 WWW.CERNYANDIVEY.COM Celebrating over 40 Years of Professional Engineering Services

September 12, 2008

Roger Rock Rock Lock Fastening Systems, Inc. 6519 Rock Creek Drive Lake Worth, FL 33467

Ultimate Load Strength Testing

TEST REPORT NUMBER:

28210

SCOPE OF TESTING

DATE OF TESTING 9/8/2008 MANUFACTURE PLANT


PRODUCT IDENTIFICATION

- Spring Bolt Connection System
- Tite-Bond Wood Glue

PROCEDURE

The test specimen was delivered to Cerny and Ivey Engineers, Inc. by the client on 9/2/2008. The test specimen consisted of two (2) sections of hardwood top rail secured together using the client's proprietary Spring Bolt system and wood glue. The Spring Bolt system used 9/16in. outside diameter springs and a 5/16in. steel rod. Wood glue was applied at the interface of the two (2) sections.


Figure 1: Top Rail Attachment






American Society of Civil Engineers American Society of Mechanical Engineers American Society of Testing & Materials Amer. Society of Heating, Refrig & A/C Engineers American Society of Plumbing Engineers Institute of Electrical & Electronic Engineers National Academy of Forensic Engineers National Fire Protection Association Society for Experimental Mechanics Society of Automotive Engineers Microscopy Society of America








The total length of the specimen was 12-1/8in. The supports of the ultimate load machine were spaced 5-3/4in. from the interface of the two (2) rail sections at the railing bottom edge. The load was applied perpendicular to the rail length directly at the interface using a 2in. outer diameter, 1in. inner diameter steel tube. The ultimate load machine crosshead was moved a constant rate of 0.183in/min with loads being recorded every 1 second by load cell CI-LC-01.

RESULTS



CONCLUSION

The maximum load held by the test specimen was 1368 lbs. Failure was due to the glue joint breaking.

If you have any questions please do not hesitate to contact us.

Respectfully submitted,

Charles G. Lester IV Laboratory Manager Christopher B. Shiver, PE Vice President – Principal Engineer