

# CERNY $\xi$ IVEY ENGINEERS, INC.

CONSULTING ENGINEERS - TESTING LABORATORY 5650 PEACHTREE PARKWAY, NORCROSS, GA 30092 TEL 770-449-6936 - FAX 770-368-1148 WWW.CERNYANDIVEY.COM Celebrating over 40 Years of Professional Engineering Services

September 4, 2008

Roger Rock Rock Lock Fastening Systems, Inc. 6519 Rock Creek Drive Lake Worth, FL 33467

## TEST REPORT NUMBER:

28205-1

DATE OF TESTING 9/2/2008 MANUFACTURE PLANT

## SCOPE OF TESTING

ASTM D7032 "Establishing Performance Ratings for Wood-Plastic Composite Deck Boards and Guardrail Systems"

## **PRODUCT IDENTIFICATION**

- Spring Bolt Connection System
- Fasco Fas-Stick Epoxy Glue (Part 1&2)
- Tite-Bond Wood Glue

## PROCEDURE

Components of the test specimen were delivered to Cerny and Ivey Engineers, Inc. by the client on 8/28/2008. The components were assembled by the client under the supervision of Cerny and Ivey Engineers, Inc. The test specimen consisted of two (2) newel posts, two (2) newel post caps, one (1) top rail, one (1) sole plate, multiple balustrades, and the proprietary Spring Bolt system that when assembled are intended to be used as an interior handrail system. The newel posts, newel post caps, top rail, sole plate and balustrades were made from a hardwood and are typical of those available at most home improvement centers.

The test specimen was anchored to a wood deck assembly, which was constructed using typical construction practices. The wood deck was secured to the floor of the testing laboratory. Three (3) pieces of 2x6 blocking were placed under the deck where the newel posts were secured. The deck was not subjected to testing.

The sole plate was secured to the edge of the deck using 2in. Brad Nails spaced 16in. apart along the joists of the deck. The sole plate was additionally anchored by #10 x 1-1/2in. square drive wood screws every 8in.The Spring Bolt System was installed into the sole plate at the location of the newel posts. The depth of the system was set, so that the system remained concealed after installation. For the condition on the 1in. high sole plate a 1-1/4in. diameter hole was drilled to a depth of 3in. to accommodate the spring. The same was done on the newel post. The Spring Bolt system used 1-1/4in. outer diameter springs measuring 3-3/4in. long and 7/8in. diameter hot rolled steel rods measuring 6in. long. This system was used on both sides.



American Society of Civil Engineers American Society of Mechanical Engineers American Society of Testing & Materials Amer. Society of Heating, Refrig & A/C Engineers American Society of Plumbing Engineers Institute of Electrical & Electronic Engineers National Academy of Forensic Engineers National Fire Protection Association Society for Experimental Mechanics Society of Automotive Engineers Microscopy Society of America CERNY É IVEY ENGINEERS, INC. 5650 Peachtree Parkway, Norcross, GA 30092 & Tel 770-449-6936 & Fax 770-368-1148 & www.cernyandivey.com

## **Figure 1: Newel Post Attachment**





Figure 2: Newel Post Spring Dimensions (provided by client, verified by C&I)



Holes were drilled for the balustrades in the sole plate and the top rail for installation. The balustrades were placed every 4in. in between the newel posts. Wood Glue was used at the sole plate only to secure the balustrades.

The top of the test specimen was assembled by taking the top rail and attaching the newel post caps with the proprietary Spring Bolt system at either end. The Spring Bolt system used 9/16in. outside diameter springs and a 5/16in. threaded rod. The Spring Bolt system was epoxied in place. The newel posts end caps were designed to fit over the newel post and be glued in place. Additionally, two (2) piece of 5/16in. threaded rod were placed at the top of each newel post near the edge, by drilling and epoxying them in place. The bottom of the newel post cap was drilled to accept the other end of the threaded rod. Epoxy was also placed in the drilled holes of the newel post caps before assembly. The top rail assembly with newel post caps was placed on top of the newel posts and epoxied in place.

5650 PEACHTREE PARKWAY, NORCROSS, GA 30092 - TEL 770-449-6936 - FAX 770-368-1148 - WWW.CERNYANDIVEY.COM





Figure 4: Top Rail Spring Dimensions (provided by client, verified by C&I)



The total length of the specimen was 82in, with 3in wide newel posts. The height of the top rail was 42 in.

#### Application Of The Load

Three (3) separate loads were placed on the test specimen to simulate the conditions set forth in the 2006 International Building Code with a minimum factor of safety of 2.5.

The initial load applied to the railing assembly was an in-fill load to the perceived weakest 12in. x 12in. section of the test specimen. The weakest area was determined to be the center of the balustrades near the center of the assembly. The infill load was set so that only three (3) balustrades were loaded. A 125lb. load was applied, in accordance with ASTM D7032.

The second load was applied uniformly to the top rail of the assembly. The top rail was determined to be the weakest component of the assembly. Pneumatic cylinders were placed approximately every 12in., as allowed by the spacing of the balustrades. A load of 235plf was applied at an angle of 58 degrees to provide a minimum of a 125plf horizontal and vertical component, in accordance with ASTM D7032.

CERNY É IVEY ENGINEERS, INC. 5650 Peachtree Parkway, Norcross, GA 30092 & Tel 770-449-6936 & Fax 770-368-1148 & www.cernyandivey.com

The third load was a concentrated load applied horizontally to the top rail at the center of the assembly. The top rail was determined to be the weakest component of the assembly. A 500lb. load was applied, in accordance with ASTM D7032.

All loads were applied in the same general direction, which is outward from where the deck would exist. All handrail testing was done in accordance with ASTM D7032.

All pressures were measured using pressure gauge CI-PG-05. Pressures were converted to force using the appropriate conversion table for the pneumatic cylinder.

#### RESULTS

Handrails passed all standardized loading tests without any visible signs of failure.

Rock Lock Handrail with Spring Bolt Connections (Tested 9/2/2008)

	2006 IBC	Passed (Y/N)		ASTM D7032 (F.S. 2.5)	Passed (Y/N)
In-Fill Load	50 lbs/ft <sup>2</sup>	Y		125 lbs/ft <sup>2</sup>	Y
Uniform Load	50 plf	Y		125 plf	Y
Concentrated Load	200lbs	Y	-	500lbs	Y

#### CONCLUSIONS

The complete handrail assemblies are in accordance with the strength requirements of the 2006 International Building Code and ASTM D7032, when installed as detailed above.

If you have any questions please don't hesitate to contact us.

Respectfully submitted,

Charles G. Lester IV Laboratory Manager Christopher B. Shiver, PE Vice President – Principal Engineer